

FOOTPATH INSPECTIONS – SARAH COOMBS

Allocated Public Right of Way : 12, 501 & 502.

FOOTPATH 12

Date Inspected:- Wednesday 7th September 2017.

The foot path is not accesible.

From the Newbridge end (Nr motorway bridge) footpath 12 cannot be accessed at all. It is completely overgrown. The stile cannot be seen and the sign is barely visible.

The field has been divided into several sections and there is no clear pathway and access for footpath users. The gates can be opened but there are horses in the fields which could escape.

The ground was dry.

This footpath needs to be cleared for access into the field and path direction across land needs to be clearly indicated.

PLEASE SEE PHOTOS.



FOOTPATH 12 ACROSS FIELDS



FOOTPATH 12

BRIDLEWAY FOOTPATH 502

Date Inspected:- Wednesday 7th September 2017.

Weather on day of inspection:- Overcast.

Signage:- One sign in good order

Recommended work required:- None

A well used track, starting at the Newbridge village end with a tarmac track, this is about 6ft wide, the track then becomes grassland to the river, there is a gate which allows access to a bridge across the river, this is about 2ft wide, after this you turn left across a field.

The bridleway is clear and well maintained, no work needs to be carried out.

FOOTPATH PUBLIC RIGHT OF WAY 501

Date Inspected:- Wednesday 7th September 2017.

Weather on day of inspection:- Overcast.

Carrying on from 502 – Having crossed the bridge – you travel into a wooded area, which provides a long horse/animal track, there are some overhanging branches. This leads into a 2m wide gravel track, with fields along its sides, it seems to be well maintained, easily accessible.

The gravel track leads out to the road, at Crock Hill, where there is a low level padlocked gate, there is enough space to move around this.

No work needs to be carried out to this footpath.

