

COPYTHORNE PARISH FOOTPATHS AND OTHER RIGHTS OF WAY CHECKLIST								
FOOTPATH/ROW NUMBER	TYPE OF RIGHT OF WAY	LENGTH OF PATH (metres)	START POINT GRID REFERENCE	END POINT GRID REFERENCE	COUNCILLOR RESPONSIBLE	DATE LAST CHECKED	OBSERVATIONS RESULTING FROM INSPECTION	NOTES
1	Bridleway	637	SU30461 11798	SU31063 11850	John Goodwin	25/07/2019	Clerk inspected, no issues of immediate concern	Joins 166/17 - NM
2	Footpath	128	SU29365 13589	SU29475 13647	John Goodwin	25/07/2019	Clerk Inspected, awaiting HCC cut, north eastern section	HCC cut due
3	Footpath	637	SU31096 14621	SU31722 14723	Graham Chillcott	17/08/2019	Overgrown throughout, lengthsman instructed to clear	
4	Footpath	1178	SU29845 15049	SU30807 14873	Steve Herra	22/08/2019	Stile needs refixing, HCC RoW to be advised	
5	Footpath	651	SU30494 14295	SU30728 14765	Sylvia Wiggins	03/09/2019	Overgrown vegetation recently cleared by Lengthsman	
6	Footpath	305	SU30791 14699	SU31073 14762	Sylvia Wiggins	03/09/2019	Finger post needs attention, HCC RoW to be advised	
7	Footpath	261	SU31192 12832	SU31430 12734	John Goodwin	25/07/2019	Clerk inspected, works needed, HCC RoW advised	Joins 166/18 - NM
8	Footpath	138	SU29960 13271	SU30005 13400	John Goodwin	25/07/2019	Clerk inspected, no issues	
9	Footpath	1051	SU29468 14297	SU29839 13962	Graham Chillcott	17/08/2019	Non -connected Electric fence to be removed. Clerk to contact	HCC cut Aug 2019
10	Footpath	1378	SU32025 17553	SU31893 18827	Simon Lucas			Joins 240/14 - W
11	Footpath	3085	SU29052 16876	SU31904 17593	Simon Lucas			
12	Footpath	178	SU30309 14532	SU30469 14551	Sylvia Wiggins	03/09/2019	Issue with finger post, some overgrowth, Clerk to check	
13	Footpath	102	SU29750 13850	SU29832 13788	John Goodwin	25/07/2019	Clerk inspected, no issues	
14	Footpath	594	SU31885 15260	SU32144 15397	Graham Chillcott	17/08/2019	Footpath sign missing, SSSI sign broken, HCC RoW advised	
15	Footpath	401	SU31885 15260	SU32064 15617	Graham Chillcott	17/08/2019	Footpath sign missing, SSSI sign broken, HCC RoW advised	
16	Footpath	299	SU31885 15260	SU32173 15320	Graham Chillcott	17/08/2019	No issues	
17	Footpath	1963	SU30006 15580	SU30751 14929	Steve Herra	22/08/2019	No issues	
18	Bridleway	989	SU30006 13396	SU30466 12873	John Goodwin	25/07/2019	Clerk inspected, no issues	
501	Footpath	450	SU29356 15440	SU29787 15550	Steve Herra	04/09/2019	Signage issues and boggy ground, to be further investigated	
502	Bridleway	125	SU29787 15550	SU29907 15517	Steve Herra	22/08/2019	No issues	
503	Restricted Byway	198	SU30428 18329	SU 30605 18421	Simon Lucas			
504a	Restricted Byway	684	SU28926 14903	SU29553 15156	T B A			Clerk to walk-Sep 9
504b	Restricted Byway	670	SU28926 14903	SU29566 15020	T B A			Clerk to walk-Sep 9

Start Point Grid reference is usually at the westernmost end of the path

End Point Grid reference is usually at the easternmost end of the path